



Examples of dust control measures in place across industry

There are several things companies can do to manage the amount of dust created, and minimise exposure to RCS amongst workers.



Enclosure
Conducting RCS producing processes in a sealed environment




Extraction / Ventilation
Ensuring that RCS is extracted and stored for secure removal



Water
Keeping processes wet to prevent dust becoming airborne



Protective equipment
(eg. face masks) preventing dust being breathed in



Good hygiene / housekeeping
Washing work clothes and vacuuming up dust produced by processes

*non-exhaustive list

The example below gives a visual representation of the improved conditions that effective ventilation and air filtering has on reducing dust in industrial workplaces – with the dust being captured by the ventilation system and stored for safe disposal:



Before



After